Revised 12/03

ACTION

DIST

BERARDINI JH

BOGNAR ES

BROOKS L BUTLER L CARPENTER M CROCKETT G A

DECK C A DEGENHART K. R. DIETER T J

DIETERLE S F

FERRERA, D W

GIACOMINI J J

LINDSAY D C

LONG J W LYLE J L MARTINEZ L A

NAGEL R E

PARKER A M RODGERS A D SHELTON D C

SPEARS M S PIZZUTO V M

TOBIN M

ZAHM C

TUOR N R WEMELT K

WILLIAMS J L

pansons

Laronatok

NESTA S NORTH K

CORRES CONTROL INCOMING LTR NO

RFLE' LED

THE 125 A RESTATE OF COLC

00229 RFQY

Bill Owens Governor DUE DATE

LTRIENC

Douglas H Benevento Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr S Denver, Colorado 80246 1530 Phone (303) 692 2000 TDD Line (303) 691 7700

http://www.cdphe.state.co.us

8100 Lowry Blvd Denver, Colorado 80230 6928

Located in Glendale Colorado

(303) 692 3090

Laboratory and Radiation Services Division



May 17, 2004

Mr Joe Legare Assistant Manager for Fnvironment and Stewardship US Department of Energy, Rocky Flats Project Office

10808 Highway 93, Unit A Golden, CO 80403-8200

RE Building 964 notification of intent to invoke the Facility Component Removal, Size Reduction, and Decontamination Activities RSOP (Component RSOP) - concurrence

Dear Mr Legare

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has received your April 21, 2004 letter (received on April 27, 2004) notifying us of your intent to utilize the Component RSOP for component removal and closure of RCRA Unit 24 associated with B964. We are hereby concurring that this activity may proceed utilizing the Component RSOP, and as described in the Closure Description Document provided

We are aware that this building has yet to be officially typed through the completion and submittal of a RLCR Building 964 was thought to be a Type 1 facility until preliminary RLC data identified radiological contamination, and a preliminary Type 2 designation was applied to B964 pending completion of, and concurrence with, the RLCR. It is our understanding that the impermeable coating was applied to the floor prior to utilizing B964 or this RCRA Unit for hazardous waste storage, that there are no records of spills, and that all liquid wastes were placed on individual secondary containment pans and not directly on the impermeable coating. As such, our concurrence is based on the understanding that this cleanup and closure of the RCRA unit needs to occur and will not change or remove the radiological contamination that resides on the exterior of the building as well as possibly under the coating, and is therefore not intended to be a radiological decontamination effort prior to actual Typing of B964

It is also our understanding that the RLCR is to be completed forthwith, and that based on the data collected to date, B964 is expected to be identified as a Type 2 facility

If you have any questions regarding this correspondence please contact me at (303) 692-3367, David Kruchek at (303) 692-3328

COR CONTROL ADMIN RECORD PATS/130

> Reviewed for Addressee Corres Control RFP

Ref Ltr #

Gary Morgan, DOE cc Mark Aguilar, EPA

RFCA Project Coordinator

Steven H Gunderson

Sincerely

Duane Parsons, KH

Administrative Records Building T130G

Karen Wiemelt, KH Dave Shelton, KH Steve Nesta, KH



DOE ORDER#



ADMIN RECORD IA-A-002148